Super Groups Risk Assessment

$\# \chi 789$ www.supergroups.com.au

This form has been completed in accordance with the Hazard Management Policy/Procedure and

Super Groups 44 wedgewood road hallam 03-97023999

Plant and Equipment Safety Management Policy/Procedure.

Overall risk rating (existing controls) highest score eg L, M, H, VH

			では、大きのでは、大きのでは、大きのでは、大きのでは、これでは、これでは、これでは、日本ので	
Diane	HAIIAM	Diant HALLAM Owner of Plant: SERIAL NO: 46589 Date assessed:	SERIAL NO: 46589	Date assessed:
l ocation:		S&S EQUIPMENT HIRE PTY LTD	HOURS: 1.2	25/10/2024
Diagt.				Review date: 25/10/2025
(Include name	KUBOTA U27-4HGA EXCAVATOR	CAVATOR		(1 yr, from RISK ASSESSMENT)
and model)				
Purpose of Plant:	CIVIL CONSTRUCTION			
Current Photo of	Current Photo of machine being assessed.	REGI	LEGISLATION	RISK ASSESSMENT LEAM
		COMPETENCIES		
		(Refer Appendix B)	OHS Legislation and/or Australian Standard to be used for further	Operator
Y		Registration required:	reference.	
		⊠ g	OHS Regulations (2017) Divisions:	HSO/Manager:
	Constant of the second	_	 1.2 OHS Responsibilities 	
		Licence/ Trade certificate required?	 1.3 Information, Instruction, 	HSR:
F		⊠ Yes	Training, Induction, Supervision	
		□I No	 2.10 Noise Part 3 Plant (including) 	Assessor: CARL HAWORTH
LUZZ	- a	Supervisor assessment required?	 3.2.25 Plant with moving parts 	Consultant: TIM JASPER
		(Induction required for this plant)	 3.2.15 Hazard Management 	
		⊠ Yes	3.2.17 Control of risk	Date Assessed: 25/10/2024
		No	AS 4024 - 2014 Safety of machinery	
		Other competency required?	AS 1788 Abrasive wheels	1
		⊠ Yes	AS 60204.1 electrical equipment for	
			industrial machines	CARL HAWORTH
	<u> </u>	Include in Safe Operating Procedure		
				(Signature) (Name)

Super Groups Risk Assessment

Super Groups 44 wedgewood road hallam 03-97023999

LEGEND

EI = Elimination

Su = Substitution

En = Engineering

☐ Is = Isolation
☐ Ad = Administration
☐ PPE = Personal Protective Equipment

www.supergroups.com.au

								NA
			⊠ PPE					Other issues No
		Induction.		Moving blade or bucket.				☑ Work pieces ejected☑ Work pieces disintegrating
		Quick hitch safety switch fitted.		Quick hitch failure.				Sharp or flying objects
	z	Warning decals fitted.		Pedestrians to keep clear 30 metres.	MEDIUM	MAJOR	UNLIKELY	Moving plant or parts
				ct with:	g into conta	utated by comir	ctured, amp	Can anyone be cut, stabbed or punctured, amputated by coming into contact with:
								NA
								□ No
	E	HIGGGROTI.						Other issues
_		Induction						collapsing/changing shape
		Do not lift above personnel decal fitted.						□ Part of the plant □
		SWL decals fitted.						
		Handrails fitted.						☐ Inability to apply brake
		Seatbelt fitted.		and servicing.			10	
		ROPS/FOPS structure fitted.		Working on plant during maintenance				☐ Under/between plant and a
		Control pod operational.		Working near pedestrians.				₹.
		Park brake operational.	N PBF	Operator not wearing seatbelt.				
		Warning decals fitted.	∑ ×	Sudden reversing.				Rolling over
		Pedals are non-slip.] [Working near structures.				
		Travel alarm and beacon fitted.	l DSI	Unexpected movement.				1
	z	Neutral start switch fitted.		Unstable ground.	MEDIUM	MAJOR	UNLIKELY	
1								Can anyone be crushed by:
N.	YN	Cultur Connois	control	Comments (le when and where hazard is present, task/activity)	Score	Consequence	Likelihood	Hazard Identified
_	ACTION required	Current Controle	I II a march to of		0.0000000000000000000000000000000000000	The state of the s		

Super Groups 44 wedgewood road hallam 03-97023999

LEGEND

EI = Elimination

Su = Substitution

En = Engineering

☐ Is = Isolation
☐ Ad = Administration
☐ PPE = Personal Protective Equipment

www.supergroups.com.au

z	Training for confined spaces must be completed before undertaking this type of work. Induction.	PPE □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □	When working in confined spaces operator may be overcome by exhaust fumes.	MEDIUM	MAJOR	RARE	Can anyone suffocate due to: Lack of oxygen Atmospheric contamination Engulfment Other issues No NA
z	Travel alarm and beacon fitted. Keep clear decals fitted. Swing area decals fitted. Induction for correct operation. ROPS/FOPS structure fitted.	□ EI	Load may shift, pedestrians to keep clear 30 metres. Unexpected plant movement	MEDIUM	MAJOR	UNLIKELY	Can anyone be struck by moving objects due to:
z		P & S E & E				?	Can anyone be burnt due to friction? Contact with moving parts or surface of the plant Material handled by the plant Other issues No
Action required Y/N	Current Controls	Hierarchy of control	Comments (ie when and where hazard is present, task/activity)	Score	Consequence	Likelihood	Hazard Identified

Super Groups 44 wedgewood road hallam 03-97023999

www.supergroups.com.au

Action required Y/N

Z

					-5	Is there a current operators manual? Yes	≺ $\overline{\omega}$
Ergonomic and adjustable seat fitted. Low stress controls fitted. Good lighting fitted. Control knobs easy to reach. Operator to take correct break periods.	N N N N N N N N N N N N N N N N N N N	Long periods of operation	MEDIUM	FIRST AID	POSSIBLE	Can anyone injured due to ergonomic issues due to: Repetitive body movement or posture Insufficient space Excessive effort (push/pull) Working at a height Seating design Poor lighting Other issues No	
High pressure fluid decals fitted. Hose clamps fitted. Hose covers fitted. Hoses in good condition and correct maintenance to be continued.	PPE □ □ □ □	to: Hydraulic hoses may burst. Radiator hoses may burst.	MEDIUM	es under high I MAJOR	fluids or gas UNLIKELY	Can anyone come into contact with fluids or gases under high pressure due to: Failure of the plant Nature of the plant Other issues No	
Current Controls	Hierarchy of control	Comments (ie when and where hazard is present, task/activity)	Score	Consequence	Likelihood	Hazard Identified	
			Equipment	Is = Isolation Ad = Administration PPE = Personal Protective Equipment	Is = Isolation Ad = Adminix PPE = Perso	LEGEND □ EI = Elimination □ Su = Substitution □ En = Engineering	

z

Super Groups 44 wedgewood road hallam 03-97023999

www.supergroups.com.au


STEP 3: ACTION REQUIRED BY MANAGER/SUPERVISOR/AUTHORISED PERSON

☑ If no actions required and residual risk is medium to very high, the activity and the hazard(s) have been transferred to the Hazard Register and communicated to the relevant personnel.

7					
H					
À					
S					
-					
\preceq					
9					
=					
(1)					

				ELITE HYDRAULIC HITCH FITTED. FLEASE KEAD AND UNDERSTAIND MANOFACTURERS HAINDBOOK DEFORE USE
				(FII IED. FLEASE READ A
				ND ONDERSTAIND MAINO
				FACTONERS HAINDBOO
				N DEL CICE COE

BLIND SPOTS



plant.

Machines have blind spots where operators may not see people or objects nearby. The following diagrams illustrate typical examples of blind spots for some common mobile

Safety around operating plant

Super Groups 44 wedgewood road hallam 03-97023999 www.supergroups.com.au